

0920Z 19 APR 65

T O P S E C R E T

DIRECTOR

25X1A

ROUTINE

TOR: 1003Z 19 APR 65
25X1A

25X1A

IN 82554
25X1A

8676

25X1A

1. MSN 0215C PENETRATED DENIED TERRITORY WITH INOPERATIVE

THE ACFT SSB HIGH VOLTAGE POWER SUPPLY FAILED WHICH CAUSED [REDACTED] TO BE INOPERATIVE. THIS MSN PLANNED FOR LONG DISTANCE OVER WATER PRIOR TO PENETRATION. TWENTY MINUTES AFTER TAKE OFF DRIVER WAS GIVEN PERMISSION TO PROCEED. DRIVER WAS INSTRUCTED DURING MSN BRIEFING BY

25X1A

[REDACTED] OPS OFFICER TO ABORT FOR [REDACTED] MALFUNCTION. DET COMDR DECIDED NOT TO ATTEMPT CONTACT ON SSB.

25X1C

2. PROJECT DIRECTIVE 50-1055-25 DOES NOT PROVIDE FOR SITUATION OF THIS TYPE. SUGGEST GO AHEAD POINT BE CHANGED TO POSITION CLOSE TO PENETRATION OR A SECOND GO AHEAD POSITION BE DESIGNATED FOR MSNS REQUIRING LONG DISTANCE PRIOR TO PENETRATION. PLEASE ADVISE.

END OF MSG

T O P S E C R E T